Oconnell Auto Body

9663 Brittany Village
Sugar Land, TX
Phone 713-555-4919

Repair Estimate

Estimate number:	EST-699884
Estimate date:	2023-08-03
Customer:	Ashley Duncan
Phone:	713-555-4888
Insurance claim:	C-1261
Vehicle:	2021 Jeep Cherokee
VIN:	119AVUAH1ZJC14527
License plate:	87HT806

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$790.95
Left quarter panel	1	$750.67
Right front door shell	1	$432.17
Body labor	19.7 hrs	$1,340.51
Paint and materials		$837.64
TOTAL		$4,151.94

Appraiser remarks

The rear quarter panel on the driver's side shows a long scrape with paint transfer and a dented edge, along with a cracked side mirror housing and a scuffed rear bumper corner. The pattern of contact runs along the side in a way that fits a sideswipe during a lane change, and the damage lines up with that account. The repair plan calls for panel straightening, refinishing of the quarter panel and bumper corner, replacement of the mirror housing, and blending of adjacent paint. The labor hours requested are in line with the work described. The invoices contain no duplicated line items or repeat charges. Nothing in the file or the owner's records suggests earlier damage to this area of the vehicle.