Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-283018
Estimate date:	12 Nov 2024
Customer:	Joel Hamilton
Phone:	281-555-5031
Insurance claim:	C-1266
Vehicle:	2023 Honda Civic
VIN:	6P4R6J8C5M87E6505
License plate:	718 6NR

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,348.15
Hood panel	1	$781.33
Left quarter panel	1	$864.52
Body labor	26.2 hrs	$1,784.89
Paint and materials		$1,274.09
TOTAL		$6,052.98

Appraiser remarks

The left rear quarter panel and rear door show crumpling consistent with a side impact at an intersection, with the damage pattern lining up well with the account given. Structural measurements taken at the shop show the frame is within tolerance, and nothing in the inspection points to older damage on this vehicle. The labor hours requested fit the scope of the work needed, and the parts list reflects what the repair requires. The billing history submitted by the shop shows no repeated charges. Recommended plan: replace the rear door and quarter panel, refinish and blend adjacent panels, and recalibrate the rear sensors before release.