Hall Auto Repair

1823 Joanna Harbor
Katy, TX
Phone 713-555-3435

Repair Estimate

Estimate number:	EST-841656
Estimate date:	2023-06-29
Customer:	George Collins
Phone:	832-555-2493
Insurance claim:	C-1270
Vehicle:	2017 Nissan Altima
VIN:	GM1F21R164Z6Z4519
License plate:	6G 3B2AFP

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$806.21
Left front fender	1	$655.61
Hood panel	1	$715.96
Body labor	22.7 hrs	$1,545.91
Paint and materials		$1,158.59
TOTAL		$4,882.28

Appraiser remarks

Vehicle inspected at the shop following a low-speed head-on impact. The front bumper cover is cracked and displaced, the radiator support shows bending consistent with a frontal hit, and the hood latch and both headlight assemblies are damaged. Crush pattern and paint transfer line up with the reported collision, and no prior damage to this vehicle is known or visible on the panels. The proposed repair plan replaces the bumper cover, hood latch, and affected lamps, straightens the support, and refinishes the front end. Labor hours are in line with the work described. Invoices submitted show a single chagre for each line item, with nothing duplicated.