White Auto Body

0084 Dana Terrace
League City, TX
Phone 713-555-0947

Repair Estimate

Estimate number:	EST-389791
Estimate date:	12/24/2024
Customer:	Jeffrey Esparza
Phone:	
Insurance claim:	C-1271
Vehicle:	2016 Toyota Camry
VIN:	
License plate:	02N J54

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,326.61
Right front door shell	1	$1,082.99
Left quarter panel	1	$936.08
Body labor	32.8 hrs	$2,231.55
Paint and materials		$1,520.88
TOTAL		$7,098.11

Appraiser remarks

The vehicle presents with crush damage along the driver side, including the front door panel, rocker area, and rear quarter panel, with the pattern consistent with a side impact at an intersection. The structural measurements show the sill and pillar alignment within expected tolerance after the hit. The repair plan calls for replacing both doors, the quarter panel, and related trim, followed by refinishing and a wheel alignment check. Parts pricing and labor hours line up with the work described, and the invoices contain no duplicated line items. No prior damage to this vehcile has been reported or found during inspection.