Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-486654
Estimate date:	12-3-24
Customer:	Dakota Jones
Phone:	
Insurance claim:	C-1276
Vehicle:	2023 Chevrolet Malibu
VIN:	6PKD22DK9NRMC9131
License plate:	MNP1364

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,613.40
Left front fender	1	$1,443.18
Left quarter panel	1	$881.12
Body labor	38.2 hrs	$2,596.60
Paint and materials		$1,116.77
TOTAL		$7,651.07

Appraiser remarks

Vehicle inspecetd at the shop following a sideswipe that occurred during a lane change. The damage to the right rear quarter panel, rear door, and adjacent trim is consistent with the reported impact, and the pattern of contact points lines up with the described mechanics of the collision. No prior damage to this vehicle is known to exist. The repair plan covers panel replacement, refinishing, and reclaibration of the blind-spot sensor. Labor hours requested fit the scope of the damage. Shop invoices reviewed show no duplicated or repeated charges. Recommend approval of the repair estimate as submitted.