White Auto Body

0084 Dana Terrace
League City, TX
Phone 713-555-0947

Repair Estimate

Estimate number:	EST-829621
Estimate date:	11/22/2024
Customer:	Jeremy Bailey
Phone:	346-555-8519
Insurance claim:	C-1277
Vehicle:	2014 Honda Civic
VIN:	G72N9RSC805BS6427
License plate:	4K367

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,304.18
Hood panel	1	$1,291.16
Left quarter panel	1	$1,157.52
Body labor	35.1 hrs	$2,388.21
Paint and materials		$1,873.87
TOTAL		$8,014.94

Appraiser remarks

Vehicle inspected at the shop following a sideswipe that occurred during a lane change. The damage to the right rear quarter panel, rear bumper cover, and tail lamp assembly lines up well with the impact as described, and the scrape pattern runs in a consistent direction across the panels. No prior damage to this vehicle is known, and the paint and body work shows no signs of older repairs. The proposed repair plan is to replace the tail lamp and bumper cover, repair and refinish the quarter panel, and blend adjacent paint. The labor hours requested are in line with the extent of the damage. The billing submitted shows no repeated chagres for the same operations.