Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-207180
Estimate date:	3-2-23
Customer:	James Rhodes
Phone:	346-555-9956
Insurance claim:	C-1281
Vehicle:	2015 Honda Civic
VIN:	
License plate:	3359

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$568.29
Left front fender	1	$563.02
Front bumper cover	1	$551.27
Body labor	19.8 hrs	$1,349.52
Paint and materials		$874.80
TOTAL		$3,906.90

Appraiser remarks

Vehicle inspected at the shop following a sideswipe sustained while changing lanes. The damage is confined to the right rear quarter panel, the rear bumper cover on that side, and the adjacent door skin, with scuffing consistent with a glancing contact from another vehicle. The pattern and height of the marks line up with the reported impact, and no older damage was found or reported on this vehicle. The proposed repair plan covers panel replacement, refinishing, and reinstallation of trim, and the labor hours requested are in line with the work described. The invoices reviewed show a single set of charges with nothing repeated. Recommend approval of the repair as written.