Williams Auto Body

998 Donovan Ford Suite 346
Pearland, TX
Phone 832-555-7510

Repair Estimate

Estimate number:	EST-991334
Estimate date:	03/06/2024
Customer:	Nicole Davis
Phone:	713-555-2793
Insurance claim:	C-1283
Vehicle:	2017 Nissan Altima
VIN:	KSZJFB535RT7Y9549
License plate:	790-VGB

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,315.27
Left quarter panel	1	$912.85
Headlamp assembly	1	$834.36
Body labor	39.5 hrs	$2,683.45
Paint and materials		$1,416.58
TOTAL		$7,162.51

Appraiser remarks

Vehicle inspected at the body shop following a sideswipe sustained while changing lanes. The damage to the right rear quarter panel, rear door, and adjacent trim is consistent with the reported impact path, and the scrape pattern and paint transfer line up with the other vehicle's described contact point. Repair plan calls for panel straightening, replacement of the damaged door skin, refinishing, and reinstallation of the trim clips. The labor hours requested fit the extent of the damage and the sequecne of work. Invoices reviewed show no repeated charges for the same operations. No prior damage to this vehicle is known from the file or from the owner's account.