Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-949505
Estimate date:	12/27/2024
Customer:	Jeff Taylor
Phone:	346-555-5701
Insurance claim:	C-1291
Vehicle:	2023 Toyota Camry
VIN:	U2K8ZUR1876B99566
License plate:	075864

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,412.05
Front bumper cover	1	$1,179.35
Hood panel	1	$1,105.85
Body labor	33.6 hrs	$2,283.78
Paint and materials		$1,502.72
TOTAL		$7,483.75

Appraiser remarks

The vehicle presents front-end damage consistent with the reported low-speed head-on impact, including a cracked bumper cover, displaced grille, and a damaged hood leading edge with bent radiator support brackets. Damage pattern and location line up with the account given at intake, and no prior damage to this vehicle is known from the records reviewed. The proposed repair plan replaces the bumper cover, grille, and hood, straightens the support brackets, and refinishes the affected panels. Labor hours are in line with the work described. The invoices reviewed show no duplicated or repeated charges, and the estimate is recommended for approval as submitted.