Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-365986
Estimate date:	2024-06-20
Customer:	Derrick Mccoy
Phone:	713-555-1006
Insurance claim:	C-1297
Vehicle:	2021 Toyota Camry
VIN:	VXLGY98L1BN177066
License plate:	FFA 437

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$235.27
Left front fender	1	$196.56
Right front door shell	1	$177.73
Body labor	5.9 hrs	$398.12
Paint and materials		$268.19
TOTAL		$1,275.87

Appraiser remarks

Rear passenger-side quarter panel shows scraping and a deep scuff running along the door skin, with the rear bumper cover cracked at the corner and the side marker lamp housing broken. The damage pattern lines up with a sideswipe during a lane change, with contact pointing to a vehicle moving alongside from the rear. The plan calls for replacing the bumper cover, refinishing the quarter panel, and repairing the door skin, with labor hours that fit the scope of this damage. Nothing in the file suggests earlier damage to this vehicle, and the invoices contain no repeated charges.