Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-663401
Estimate date:	21 Aug 2024
Customer:	Connie Crane
Phone:	281-555-3506
Insurance claim:	C-1301
Vehicle:	2022 Nissan Altima
VIN:	22MKKKUA6NFWD5216
License plate:	0ZV 766

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$880.84
Left front fender	1	$1,071.42
Left quarter panel	1	$868.49
Body labor	24.9 hrs	$1,694.10
Paint and materials		$1,277.41
TOTAL		$5,792.26

Appraiser remarks

Inspection of the driver's side shows a dented rear quarter panel, a cracked rear door skin, and a bent rear wheel rim, with scuffing that runs along the lower sill. Most of this damage lines up well with a side impact at an intersection. Parts needed are a new door shell, a quarter panel for panel replacement, and a rim, with refinishing and frame measurement to follow. The labor hours requested match the extent of the damage, and the invoices contain no repeated charges. No earlier damage to this vehicle is known from our records or the owner's account. Repair is recommended as itemized.