Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-920169
Estimate date:	2025-03-20
Customer:	Stacy Hull
Phone:	832-555-7532
Insurance claim:	C-1302
Vehicle:	2022 Toyota Camry
VIN:	4ALE3HSX3PEE84071
License plate:	KMJ-835

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$512.62
Hood panel	1	$527.71
Right front door shell	1	$494.65
Body labor	13.0 hrs	$887.20
Paint and materials		$639.69
TOTAL		$3,061.87

Appraiser remarks

The vehicle presented with deformation to the rear quarter panel and rear door, with the dents sitting on the opposite side from the one described in the loss report and at a noticeably lower height than a side impact at an intersection would typically produce. Paint transfer and crush depth were checked against the stated mechanism, and the pattern does not line up with it. The repair plan calls for panel straightening, replacement of the rear door skin, and refinishing of the affected panels, with labor hours that fit the damage shown. Invoices reviewed contain no repeated charges. No prior damage to the vehicle is on record. Recommend a follow-up inspection of the impact points before the estimate is finalized.