Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-428274
Estimate date:	16 Nov 2023
Customer:	Diana Smith
Phone:	281-555-9407
Insurance claim:	C-1306
Vehicle:	2018 Honda Civic
VIN:	S3ZGW8A04JHWK2344
License plate:	694 QLZ

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,337.97
Front bumper cover	1	$1,216.91
Right front door shell	1	$658.19
Body labor	31.4 hrs	$2,135.63
Paint and materials		$1,354.05
TOTAL		$6,702.75

Appraiser remarks

The rear quarter panel and passenger-side rear door show scraping, a creased edge along the lower body line, and paint transfer consistent with a sideswipe during a lane change. The damage pattern matches the impact as described by the insured. No prior damage to this vehicle is known from the file or from the inspection. Labor hours for panel straightening, refinishing, and blending fit the extent of the damage. Two similar charges on the same day are under review and will be confirmed before the estimate is finalized. The repair plan is to replace the rear door skin, repair and refinish the quarter panel, and recheck alignment of the adjacent trim before release.