Hernandez Auto Body

9176 Jennifer Lights
League City, TX
Phone 346-555-3201

Repair Estimate

Estimate number:	EST-124916
Estimate date:	November 16, 2023
Customer:	Chelsea Terry
Phone:	281-555-4527
Insurance claim:	C-1307
Vehicle:	2018 Chevrolet Malibu
VIN:	VB1TWVD4XFDGS9780
License plate:	FBW 753

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$296.47
Left quarter panel	1	$229.58
Headlamp assembly	1	$142.13
Body labor	8.7 hrs	$588.73
Paint and materials		$254.68
TOTAL		$1,511.59

Appraiser remarks

The vehicle shows damage along the right rear quarter panel and rear bumper cover, with scrapes and a crease running toward the wheel arch, which fits the sideswipe the insured described during a lane change. The repair plan calls for replacing the bumper cover, repairing and refinishing the quarter panel, and replacing the damaegd rear marker light. The labor hours submitted match the scope of this work. The parts and lbaor lines on the invoices are not duplicated, and there is no record of prior damage to this vehicle in the file.