Oconnell Auto Body

9663 Brittany Village
Sugar Land, TX
Phone 713-555-4919

Repair Estimate

Estimate number:	EST-145158
Estimate date:	2023-01-18
Customer:	Christine Solomon
Phone:	281-555-0443
Insurance claim:	C-1310
Vehicle:	2020 Nissan Altima
VIN:	1ZWYN5LS48CW39922
License plate:	404-MRQ

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$461.13
Hood panel	1	$325.01
Left quarter panel	1	$245.04
Body labor	8.7 hrs	$594.15
Paint and materials		$286.30
TOTAL		$1,911.63

Appraiser remarks

The rear bumper cover is cracked and the left quarter panel shows a crease with paint transfer along its lower edge, which lines up with the impact described on the claim. The repair plan calls for replacing the bumper cover, straightening and refinishing the quarter panel, and recalibrating the parking sensors. The labor hours requested fit the extent of the damage shown in the photographs. Nothing in the parts or labor records repeats, and no prior damage to this vehicle is on file or known to the shop.