Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-400829
Estimate date:	March 18, 2025
Customer:	Lorraine Allen
Phone:	281-555-8962
Insurance claim:	C-1313
Vehicle:	2019 Chevrolet Malibu
VIN:	044S1F1W6XPZN7366
License plate:	OPC 573

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$995.85
Front bumper cover	1	$790.37
Left front fender	1	$787.72
Body labor	24.2 hrs	$1,647.22
Paint and materials		$794.05
TOTAL		$5,015.21

Appraiser remarks

Rear quarter panel and bumper cover show crumpling consistent with a side-to-rear impact while turning left, and the pattern of deformation lines up with the account given. Parts and labor for the proposed repair plan are reasonable for the extent of the damage, and the labor hours match the work needed to restore the panels and align the bumper. The shop's invoice lists each item once with no repeated charges. Nothing in the file points to earlier damage on this vehicle, so the estimate covers only the current loss.