Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

Repair Estimate

Estimate number:	EST-601137
Estimate date:	06/09/2025
Customer:	Valerie Serrano
Phone:	832-555-0352
Insurance claim:	C-1314
Vehicle:	2019 Kia Sorento
VIN:	D73TB2HU23E5R7863
License plate:	867-SYI

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$318.68
Right front door shell	1	$297.37
Left quarter panel	1	$169.55
Body labor	11.3 hrs	$542.66
Paint and materials		$243.22
TOTAL		$1,571.48

Appraiser remarks

The vehicle shows front-quarter damage with a crease and paint transfer, but the dents sit on the opposite side and lower than the impact described for a left turn, so the pattern does not line up with the account given. The supporting invoices show no repeated charges for the same parts or labor. Labor hours look somewhat high for this scope of work and should be reviewed against the parts list. No prior damage to this vehicle is on record. Recommended plan: replace the front bumper cover, repair the crease, refinish the affected panels, and verify the hours before approval.