Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-323681
Estimate date:	September 2, 2023
Customer:	Maria Juarez
Phone:	281-555-2325
Insurance claim:	C-1321
Vehicle:	2017 Kia Sorento
VIN:	LKBNMUR09LHJ72290
License plate:	056739

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$371.33
Right front door shell	1	$376.99
Hood panel	1	$274.19
Body labor	12.9 hrs	$878.22
Paint and materials		$479.29
TOTAL		$2,380.02

Appraiser remarks

Vehicle inspected at the shop following a side impact at an intersection. The damage to the driver's side is largely consistent with the impact as described, affecting the front door, rear door, and quarter panel, with associated sill and mirror-housing damage. No prior damage to this vehicle has come to light during the inspection. The repair plan calls for panel replacement, refinishing, and recalibration of the side-mounted sensors. Labor hours submitted for each operation fit the scope of the damage shown, and the parts and charges listed on the invoices show no repeated entries. Recommend approval of the estimate as written.