Guerrero Auto Body

83242 Brian Turnpike Suite 994
League City, TX
Phone 713-555-7464

Repair Estimate

Estimate number:	EST-377822
Estimate date:	2024-02-07
Customer:	Anthony Odom
Phone:	281-555-3122
Insurance claim:	C-1333
Vehicle:	2012 Ford F-150
VIN:	0YKVF36K7DKHG4108
License plate:	2HPJ 49

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,007.89
Hood panel	1	$956.33
Headlamp assembly	1	$900.53
Body labor	29.5 hrs	$2,004.33
Paint and materials		$1,037.38
TOTAL		$5,906.46

Appraiser remarks

The rear quarter panel and left rear door show the main crush and paint transfer, which fits the side-swipe described for a vehicle turning left into the path of the claimant. Most of the damage lines up well with that impact, and the repair labor hours shown are consistent with the panels needing replacement and refinishing. A few older scratches on the bumper cover may predate this incident and have been noted separately. Two siimlar line items billed on the same day are still under review before final approval. Repair plan: replace the rear door skin, repair and refinish the quarter panel, and reassess after parts arrive.