Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-613586
Estimate date:	05/15/2024
Customer:	Christina Ellis
Phone:	832-555-4379
Insurance claim:	C-1335
Vehicle:	2010 Jeep Cherokee
VIN:	M9REAAGJXL4B51333
License plate:	7P X0023

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,888.01
Front bumper cover	1	$1,468.92
Right front door shell	1	$1,255.20
Body labor	62.5 hrs	$3,002.20
Paint and materials		$1,460.90
TOTAL		$9,075.23

Appraiser remarks

The left rear quarter panel and rear door show scrapes, a creased edge, and paint transfer consistent with a sideswipe while changing lanes, and the damage pattern mathces the impact as described. The repair plan calls for panel replacement, refinishing, and blending into adjacent paint. Two similar charges appear on the same day and are being checked before approval. The labor hours look a little high for this scope of damage and will be reviewed. A few old scratches near the rear wheel arch may predtae this incident and are noted separately for the adjuster.