Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-773686
Estimate date:	11-18-24
Customer:	Karla Wilson
Phone:	281-555-9504
Insurance claim:	C-1346
Vehicle:	2013 Hyundai Elantra
VIN:	A873MD6S1XMV71566
License plate:	129C

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$860.14
Front bumper cover	1	$759.42
Headlamp assembly	1	$728.84
Body labor	27.3 hrs	$1,858.56
Paint and materials		$945.77
TOTAL		$5,152.73

Appraiser remarks

Front-end damage is consistent with a low-speed head-on impact, with the bumper cover, hood leading edge, and both headlamp assemblies showing crushing and cracks. The radiator support and upper crossmember appear bent, though it is not yet clear whether every component listed was damaged in this event or some was affected earlier. No prior damage to the vehicle is known to this writer. The proposed plan replaces the cover, hood, and lamps, straightens the support, and refinishes the affected panels. The labor hours requested match the scope of visible damage, and the invoices received show no repeated charges for the same operation.