Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-120191
Estimate date:	September 28, 2024
Customer:	Gabriel Hernandez
Phone:	281-555-7601
Insurance claim:	C-1352
Vehicle:	2024 Chevrolet Malibu
VIN:	4EJ0UWHM1MNS56611
License plate:	9-64057A

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$991.65
Hood panel	1	$655.28
Left front fender	1	$676.83
Body labor	29.1 hrs	$1,978.78
Paint and materials		$810.82
TOTAL		$5,113.36

Appraiser remarks

Inspection confirms damage consistent with a siedswipe along the right rear quarter, including a scraped and dented rear door, a cracked taillight lens, and scuffing that runs toward the fender. The marks line up with the account of a lateral contact during a lane change. Parts needed are a replacement door shell, a new lens assembly, and refinishing of the adjoining panel. Labor hours in the estimate fit the extent of the work shown. The invoices submitted contain no repeated line items. Nothing in the file points to prior damage at this location, so the proposed repair covers only the current loss.