Mitchell Collision Center

7738 Leon Underpass Apt. 148
Baytown, TX
Phone 713-555-3433

Repair Estimate

Estimate number:	EST-950389
Estimate date:	03/09/2025
Customer:	Leah Bowen
Phone:	
Insurance claim:	C-1355
Vehicle:	2011 Jeep Cherokee
VIN:	0RX3M58E02HMZ8830
License plate:	VPF 919

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,545.52
Right front door shell	1	$1,669.42
Left quarter panel	1	$1,221.25
Body labor	36.7 hrs	$2,494.67
Paint and materials		$1,858.08
TOTAL		$8,788.94

Appraiser remarks

The vehicle presents right-side damage consistent with a siedswipe during a lane change: a scuffed and creased rear quarter panel, a cracked passenger-side mirror housing, and paint transfer along the door skin. The damage pattern lines up with the impact as described. The proposed repair plan calls for panel straightening, refinishing of the door and quarter panel, and replacement of the mirror assembly. The labor hours requested fit the extent of the damage. No prior damage to the vehicle is known, and the parts and charges listed on the invoices show no repeated entries. Recommend approval of the repair as presented.