Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-835719
Estimate date:	2023-04-09
Customer:	Alyssa Gutierrez
Phone:	346-555-3816
Insurance claim:	C-1359
Vehicle:	2011 Honda Civic
VIN:	CC2A32NUXU8T45723
License plate:	136 NCS

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$341.22
Headlamp assembly	1	$475.04
Front bumper cover	1	$353.07
Body labor	10.8 hrs	$732.96
Paint and materials		$437.84
TOTAL		$2,340.13

Appraiser remarks

The vehicle presents with front-quarter damage consistent with a left-turn collision, including a cracked bumper cover, a deformed fender, and a damaged headlamp assembly. The repair plan calls for replacing the bumper cover and headlamp, straightening and refinishing the fender, and recalibrating the driver-assist camera. The labor hours submitted fit the damage described. It is not yet clear whether all of the listed damage stems from this impact, since file records show similar major front damage from an earlier accident that was never reported. Two similar charges submitted on the same day are also being checked before approval.