Hernandez Auto Body

9176 Jennifer Lights
League City, TX
Phone 346-555-3201

Repair Estimate

Estimate number:	EST-311653
Estimate date:	September 25, 2023
Customer:	Cynthia Steele
Phone:	346-555-0385
Insurance claim:	C-1361
Vehicle:	2020 Honda Civic
VIN:	EAVETDF96R90N3898
License plate:	NU 86296

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$266.29
Left quarter panel	1	$157.48
Right front door shell	1	$139.79
Body labor	6.6 hrs	$450.60
Paint and materials		$197.97
TOTAL		$1,212.13

Appraiser remarks

Inspection confirms a sideswipe pattern along the right rear quarter panel, with scraping and a deep dent running into the rear door skin and a cracked taillight lens on the same side. Damage is mostly in line with the impact described by the insured. Repair plan calls for replacing the rear bumper cover, straightening the door, refinishing the affected panels, and installing a new lens assembly. The labor hours requested fit the extent of the work. The shop's invoices show no repeated charges, and no earlier damage to this vehicle is known from our records. Estimate is recommended for approval as submitted.