Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-790964
Estimate date:	08/03/2023
Customer:	Crystal Morgan
Phone:	281-555-6704
Insurance claim:	C-1362
Vehicle:	2019 Toyota Camry
VIN:	6N2XUAHA4W9B30121
License plate:	208 HIF

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$704.80
Left quarter panel	1	$794.10
Headlamp assembly	1	$641.82
Body labor	25.6 hrs	$1,740.09
Paint and materials		$879.87
TOTAL		$4,760.68

Appraiser remarks

The front bumper cover is cracked across the center and the upper radiator support has a bend consistent with a frontal impact of this type, and the damage pattern lines up with the collision as described. The repair plan calls for replacing the bumper cover, straightening the support, and refinishing the adjacent panels. Labor hours are in line with the work required for this damage. The invoices reviewed show no repeated charges. A few light scratches on the rear quarter panel appear older than this loss and are noted separately, but they are not part of the proposed repair.