Hernandez Auto Body

9176 Jennifer Lights
League City, TX
Phone 346-555-3201

Repair Estimate

Estimate number:	EST-955140
Estimate date:	October 28, 2023
Customer:	Benjamin Ferguson
Phone:	713-555-7426
Insurance claim:	C-1364
Vehicle:	2015 Toyota Camry
VIN:	VY7SV1TR5CC6U6884
License plate:	TRG3812

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,386.00
Right front door shell	1	$1,217.36
Left quarter panel	1	$807.73
Body labor	31.7 hrs	$2,158.07
Paint and materials		$982.48
TOTAL		$6,551.64

Appraiser remarks

Side impact to the driver's door and rear quarter panel, consistent with a broadside collision at an intersection. Visible crush to the door skin and intrusion at the B-pillar trim, with a cracked rear lamp assembly and scuffing along the rocker. Repair plan calls for door replacement, quarter panel repair and refinish, and lamp replacement. Labor hours fit the damage shown and the invoice lines show no repeated charges. No prior damage to this vehicle is known to us. Some lower rocker and wheel-well marks may pre-date this event and could not be fully confirmed from the photos, so a teardown inspection is recommended before final approval of those items.