Rogers Auto Repair

23623 Robert Isle
League City, TX
Phone 346-555-0366

Repair Estimate

Estimate number:	EST-387744
Estimate date:	2024-05-19
Customer:	Michael Chavez
Phone:	713-555-4380
Insurance claim:	C-1370
Vehicle:	2010 Jeep Cherokee
VIN:	23HV01AA9Y1VX3979
License plate:	424-KVF

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$890.12
Left quarter panel	1	$606.86
Headlamp assembly	1	$706.50
Body labor	30.8 hrs	$1,479.76
Paint and materials		$733.46
TOTAL		$4,416.70

Appraiser remarks

Vehicle presented with side-impact damage consistent with the described intersection collision, centered on the driver-side rear quarter panel and adjacent door skin. Intrusion is limited and the crush pattern follows the reported direction of force. Repair plan calls for panel replacement, refinishing, and alignment checks on the rear door hinge area. Labor hours appear slightly elevated for the extent of the damage and should be reviewed against the standard time guide before approval. Shop invoices show no duplicated charges. No prior damage to this vehicle is on record.