Jenkins Auto Repair

106 Mcbride Coves
Sugar Land, TX
Phone 281-555-3872

Repair Estimate

Estimate number:	EST-297999
Estimate date:	August 6, 2023
Customer:	Glenda Heath
Phone:	832-555-3269
Insurance claim:	C-1371
Vehicle:	2023 Chevrolet Malibu
VIN:	87EDV4GH7LK2V6245
License plate:	AAK-355

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$418.54
Front bumper cover	1	$411.46
Left quarter panel	1	$269.60
Body labor	16.5 hrs	$790.08
Paint and materials		$472.43
TOTAL		$2,362.11

Appraiser remarks

The rear quarter panel and left rear bumper cover show crushed and scraped areas that line up well with a side-to-rear strike from a vehicle turning across the path, which fits the account given at the scene. Nothing in the file points to earlier damage on this vehicle. The shop's labor hours run slightly above what I would expect for this scope, so I have asked for a line-by-line breakdown before approving that portion. The plan is to repalce the bumper cover, repair and refinish the quarter panel, and recalibrate the rear sensor. Parts pricing and paint hours look reasonable, and the invoices show no repeated charges.