# Mitchell Collision Center

7738 Leon Underpass Apt. 148
Baytown, TX
Phone 713-555-3433

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-102291 |
| **Estimate date:** | 10/02/2023 |
| **Customer:** | Connie Peters |
| **Phone:** | 713-555-5727 |
| **Insurance claim:** | C-1373 |
| **Vehicle:** | 2023 Nissan Altima |
| **VIN:** | ZPAG8HEHXSDX65646 |
| **License plate:** | 063-BCEX |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Front bumper cover | 1 | $434.14 |
| Headlamp assembly | 1 | $315.95 |
| Left front fender | 1 | $225.52 |
| Body labor | 32.6 hrs | $717.39 |
| Paint and materials | | $401.28 |
| TOTAL | | $2,094.28 |

### Appraiser remarks

The rear quarter panel and bumper cover on the vehicle show damage consistent with a side impact while turning left, and the pattern matches the reported collision. Nothing in the file points to earlier damage on this vehicle. The billing history contains no repeated charges. However, the labor hours requested are roughly three times what this scope of repair would normally require, so I have asked the shop to justify each line before approval. Recommended plan: replace the bumper cover, repair and refinish the quarter panel, and reset the taillight assembly, with hours revised to a standard range.