Hernandez Auto Body

9176 Jennifer Lights
League City, TX
Phone 346-555-3201

Repair Estimate

Estimate number:	EST-284027
Estimate date:	April 20, 2025
Customer:	Hannah Harris
Phone:	832-555-9171
Insurance claim:	C-1377
Vehicle:	2011 Toyota Camry
VIN:	BC6R8X0N9GGAV8828
License plate:	Z45 5QA

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$555.09
Right front door shell	1	$324.60
Left front fender	1	$360.95
Body labor	12.3 hrs	$837.79
Paint and materials		$504.58
TOTAL		$2,583.01

Appraiser remarks

The vehicle presents damage along the right rear quarter panel and rear door, cosnistent with a sideswipe during a lane change. The scraped paint, creased sheet metal and cracked taillight lens line up with the contact pattern described by the parties. Repair will involve replacing the taillight assembly, straightening and refinishing the rear door, and blending the adjacent quarter panel. The labor hours requested fit the extent of this damage. Records reviewed show no repeated charges, and nothing in the file indicates earlier damage to this vehicle. The estimate is recommended for approval as written.