Patton Collision Center

518 Smith Manor Suite 165
League City, TX
Phone 281-555-6284

Repair Estimate

Estimate number:	EST-338101
Estimate date:	06/18/2023
Customer:	Suzanne Nelson
Phone:	832-555-2166
Insurance claim:	C-1381
Vehicle:	2016 Nissan Altima
VIN:	79T9RPELXDTZL2738
License plate:	6945

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,490.97
Headlamp assembly	1	$1,242.89
Left front fender	1	$1,206.91
Body labor	50.3 hrs	$2,414.05
Paint and materials		$1,484.34
TOTAL		$7,839.16

Appraiser remarks

The vehicle presents with damage to the rear quarter panel and rear bumper cover on the driver side. The dents sit lower and on a different side than the sideswipe described by the insured, so the damage pattern does not line up with the reported event and this will need follow-up. Itemized charges show no repeated line items. Labor hours run slightly above typical for this scope, and I recommend a line-by-line review. No prior damage to this vehicle is on file. Proposed repair is panel straightening, refinishing of the rear quarter, and replacement of the bumper cover, pending the review.