Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-279074
Estimate date:	3-13-25
Customer:	Robert Wolf
Phone:	832-555-2177
Insurance claim:	C-1382
Vehicle:	2016 Hyundai Elantra
VIN:	E9NSX96501HP99511
License plate:	216 YQ5

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,097.54
Left front fender	1	$988.71
Headlamp assembly	1	$810.21
Body labor	27.6 hrs	$1,874.67
Paint and materials		$1,439.05
TOTAL		$6,210.18

Appraiser remarks

Inspection of the driver-side doors, rear quarter panel and B-pillar shows crushed metal and cracked trim consistent with a side impact at an intersection. Most of the deformation lines up with the accuont of how the collision occurred. The repair plan calls for replacing the front door shell, straightening the rear quarter panel, refinishing affected panels and replacing the side mirror assembly. Labor hours requested fit the extent of the damage, and the parts and charges listed on the invoice do not repeat. No prior damage to this vehicle is known from our records or the owner's report.