Freeman Collision Center

4948 Zachary Field Apt. 367
Sugar Land, TX
Phone 346-555-7701

Repair Estimate

Estimate number:	EST-236768
Estimate date:	3 Mar 2025
Customer:	Christina Ramirez
Phone:	346-555-6188
Insurance claim:	C-1384
Vehicle:	2020 Jeep Cherokee
VIN:	DD6P2FA77TNP69859
License plate:	0X250

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,547.77
Front bumper cover	1	$1,797.60
Headlamp assembly	1	$858.36
Body labor	45.0 hrs	$3,060.46
Paint and materials		$1,579.49
TOTAL		$8,843.68

Appraiser remarks

Appraiser's remarks: The right rear quarter panel and rear bumper cover show scuffing, a cracked corner of the bumper cover, and a dented lower door skin consistent with a sideswipe during a lane change. It is not clear whether all of the damage came from this impact, so the rear bumper support area should be checked once the cover is off. No earlier damage to the vehicle is known. The bills show no repeated charges, and the repiar labor hours fit the damage described. Plan: repair and refinish the quarter panel, replace the bumper cover, and blend adjacent panels for color match.