Mendoza Collision Center

47116 Jones Roads
Houston, TX
Phone 281-555-2941

Repair Estimate

Estimate number:	EST-674790
Estimate date:	October 4, 2024
Customer:	Sean Padilla
Phone:	281-555-3918
Insurance claim:	C-1385
Vehicle:	2014 Chevrolet Malibu
VIN:	3HK97XLD9GN1J4856
License plate:	40-4416F

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$310.95
Right front door shell	1	$406.77
Hood panel	1	$270.79
Body labor	10.5 hrs	$714.04
Paint and materials		$428.78
TOTAL		$2,131.33

Appraiser remarks

Rear quarter panel and left taillight assembly show crumpling and cracked lens, consistent with a rear-side impact while the other vehicle was turning left. Damage pattern matches the account given. Repair plan calls for panel replacement, paint blending, and lamp assembly swap, with lbaor hours in line with the scope. No prior damage to this vehicle is on record. Two similar charges posted to the same account on the same day are under review before payment is released.