Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-422999
Estimate date:	2024-04-13
Customer:	Bryan Malone
Phone:	832-555-5626
Insurance claim:	C-1390
Vehicle:	2019 Toyota Camry
VIN:	66TSZBXA56Z6J6340
License plate:	74-Z181

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,397.72
Headlamp assembly	1	$1,264.17
Left front fender	1	$1,417.26
Body labor	41.5 hrs	$2,823.77
Paint and materials		$1,787.92
TOTAL		$8,690.84

Appraiser remarks

Inspection of the right rear quarter panel and rear bumper cover shows scraping, a cracked corner of the bumper cover, and a dented rear door skin, which fits the reported sideswipe while changing lanes. The damage is mostly in line with the described impact, and the lower control arm area is undamaged. The proposed repair plan calls for panel straightening, refinishing of the door and quarter panel, and replacement of the bumper cover. The labor hours submitted fit the damage shown. The billing records show no repeated charges, and no earlier damage to the vehicle is known from the file or the owner's records. Recommend approval of the repair plan as written.