Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-466990
Estimate date:	2023-08-13
Customer:	Travis Davis
Phone:	713-555-0286
Insurance claim:	C-1393
Vehicle:	2013 Nissan Altima
VIN:	BYEL3B976646M4916
License plate:	1E059

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,917.52
Left front fender	1	$1,735.37
Left quarter panel	1	$1,463.47
Body labor	43.9 hrs	$2,984.25
Paint and materials		$1,331.64
TOTAL		$9,432.25

Appraiser remarks

Rear bumper cover cracked across the center with the left tail lamp housing broken and the trunk lid edge scuffed, all consistent with the reported parking lot impact. The damage pattern lines up well with the way the two vehicles met, and nothing suggests older or unrelated harm to this vehicle. The repair plan calls for replacing the bumper cover and tail lamp assembly, refinishing the trunk lid edge, and recalibrating the parking sensors. Labor hours submitted fit the scope of this work. The invoices we reviewed show no repeated charges for the same operations. Recommend approval as submitted.