# Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-928478 |
| **Estimate date:** | 2023-01-30 |
| **Customer:** | Perry Wilson |
| **Phone:** | |
| **Insurance claim:** | C-1401 |
| **Vehicle:** | 2021 Chevrolet Malibu |
| **VIN:** | PRVU12GB7FTMJ7098 |
| **License plate:** | USJ 3380 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Left quarter panel | 1 | $1,218.82 |
| Hood panel | 1 | $1,031.20 |
| Front bumper cover | 1 | $842.07 |
| Body labor | 30.0 hrs | $2,038.89 |
| Paint and materials | | $1,103.52 |
| TOTAL | | $6,234.50 |

### Appraiser remarks

Inspection of the rear quarter panel and left taillamp assembly shows crush and scuffing consistent with a side-on contcat during a left turn, and the pattern of deformation lines up with the account given. Structural measurements were taken and the bracket and bumper cover replacement is proposed, with paint blending on the adjacent panel. The labor hours requested fit the extent of the work shown. No prior damage to this vehicle is known from our records or the photos provided. Two similar invoice charges posted on the same day are under review with the shop before payment is approved.