Mendoza Collision Center

47116 Jones Roads
Houston, TX
Phone 281-555-2941

Repair Estimate

Estimate number:	EST-869880
Estimate date:	March 23, 2025
Customer:	Courtney Webb
Phone:	346-555-5458
Insurance claim:	C-1403
Vehicle:	2012 Honda Civic
VIN:	ZP58HVVWXLC4S1631
License plate:	XOQ 611

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,950.13
Hood panel	1	$1,294.85
Headlamp assembly	1	$1,383.70
Body labor	42.1 hrs	$2,859.89
Paint and materials		$1,531.17
TOTAL		$9,019.74

Appraiser remarks

The vehicle presents mainly rear bumper cover fracture, right taillamp assembly cracking, and deformation of the trunk lid edge, which corresponds well with the rear-to-front contact described at the lot. Replacement of the bumper cover, lamp assembly, and a refinish of the lid is the proposed plan. Labor time is consistent with the extent of the work, and the line items on the invoices do not repeat any charges. A few light scratches low on the quarter panel may predate this incident, and I have noted them separately so they are not included in the repair scope.