Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-532624
Estimate date:	2025-05-31
Customer:	Scott Fox
Phone:	346-555-5203
Insurance claim:	C-1405
Vehicle:	2024 Nissan Altima
VIN:	Y5J3UMUMXV1T59003
License plate:	102 NGS

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$747.96
Front bumper cover	1	$682.86
Left front fender	1	$519.73
Body labor	17.4 hrs	$1,183.75
Paint and materials		$791.85
TOTAL		$3,926.15

Appraiser remarks

Vehicle was struck on the front driver-side corner while turning left. The damage present on the front bumepr cover, the driver-side headlamp assembly, and the fender is consistent with the impact described, and the damage pattern lines up with that account. Repair plan calls for replacing the bumper cover and headlamp, repairing the fender, and refinishing the affected panels. The labor hours requested fit the extent of the damage shown. The invoices submitted contain no repeated charges. No prior damage to this vehicle is known from our records or the inspection.