Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-106344
Estimate date:	2025-02-05
Customer:	Laurie Gonzales
Phone:	832-555-5982
Insurance claim:	C-1410
Vehicle:	2017 Toyota Camry
VIN:	58AZWM4B54YF16703
License plate:	93S DJ7

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$480.43
Headlamp assembly	1	$448.66
Front bumper cover	1	$298.93
Body labor	13.1 hrs	$888.91
Paint and materials		$495.66
TOTAL		$2,612.59

Appraiser remarks

The estimate was reviewed on the vehicle. The reported impact was a left-turn collision at the front, but the deformation sits on the right rear quarter panel and at a lower height than a front-side srtike would normally produce, so the described mechanism does not account for the damage pattern. Two similar repair charges appear under the same visit and are being checked before any approval. The labor hours fit the visible damage, and the parts list is reasonable for the work. No earlier damage to this vehicle is known. Repair plan: replace the right rear quarter panel, blend and refinish adjacent surfaces, and recheck the rear alignment before release.