Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-577223
Estimate date:	02/11/2023
Customer:	William Jones
Phone:	832-555-2893
Insurance claim:	C-1412
Vehicle:	2010 Jeep Cherokee
VIN:	AF44VX0L61TBM8400
License plate:	6YI 660

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$877.32
Hood panel	1	$754.88
Left front fender	1	$743.76
Body labor	41.5 hrs	$1,990.54
Paint and materials		$1,222.86
TOTAL		$5,589.36

Appraiser remarks

The rear quarter panel and bumper cover on the vehicle show damage consistent with the impact described, with the crease and paint transfer lining up with a left-turn collision. Parts and labor are itemized, and the billing reflects no repeated charges. The labor hours run a little high for this scope of damage, so the shop should justify the time on the body work. No prior damage to this vehicle is known. The repair plan is to replace the bumper cover, repair and refinish the quarter panel, and recalibrate the rear sensor. Approval is recommended once the labor figures are reviewed.