Guerrero Auto Body

83242 Brian Turnpike Suite 994
League City, TX
Phone 713-555-7464

Repair Estimate

Estimate number:	EST-854887
Estimate date:	2023-08-26
Customer:	David Burns
Phone:	346-555-0740
Insurance claim:	C-1424
Vehicle:	2016 Jeep Cherokee
VIN:	0TB9LMMV3N33U4194
License plate:	3634

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,219.56
Left front fender	1	$902.45
Right front door shell	1	$951.14
Body labor	36.4 hrs	$2,473.35
Paint and materials		$1,350.52
TOTAL		$6,897.02

Appraiser remarks

The front bumper cover is cracked across the center and the upper radiator spuport shows bending consistent with a low-speed frontal impact. The hood latch has shifted and both headlamp assemblies are cracked at the mounts. Damage to the grille and the lower air dam lines up with what was described at the scene. The plan is to replace the bumper cover, radiator support, hood latch, and both headlamps, followed by a refinish of the front end and a wheel alignment check. The labor hours on the estimate fit the scope of this damage. The invoices submitted show no repeated charges. No prior damage to this vehicle is known to the shop or the owner.