Hernandez Auto Body

9176 Jennifer Lights
League City, TX
Phone 346-555-3201

Repair Estimate

Estimate number:	EST-119923
Estimate date:	April 21, 2023
Customer:	Kyle Williams
Phone:	832-555-6964
Insurance claim:	C-1425
Vehicle:	2023 Hyundai Elantra
VIN:	
License plate:	VJP 4697

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,347.85
Left quarter panel	1	$1,419.96
Front bumper cover	1	$1,145.09
Body labor	55.4 hrs	$2,661.27
Paint and materials		$1,549.45
TOTAL		$8,123.62

Appraiser remarks

Inspection of the left rear quarter panel and rear door shows deformation and paint transfer consistent with the side impact at the intersection, and the crush pattern lines up with the account given. Repair plan calls for replacing the rear door shell, straightening the quarter panel, and refinishing both panels. Invoice line items show no duplicated charges. Labor hours appear slightly high for this scope of work and should be reviewed against standard repair times. A few older scratches on the lower door may predate this loss and were noted separately for reference.