Jones Auto Body

738 Jennifer Ports Suite 376
Sugar Land, TX
Phone 713-555-1656

Repair Estimate

Estimate number:	EST-487064
Estimate date:	03/02/2023
Customer:	Lindsey Walker
Phone:	832-555-6686
Insurance claim:	C-1434
Vehicle:	2023 Chevrolet Malibu
VIN:	
License plate:	

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$350.53
Right front door shell	1	$288.43
Hood panel	1	$342.33
Body labor	31.5 hrs	$692.94
Paint and materials		$450.24
TOTAL		$2,124.47

Appraiser remarks

The vehicle shows a side impact to the driver's rear quarter pnael and rear door, with crushed metal along the lower sill and a cracked taillight lens. Most of this damage lines up with the collision as described. A few older scratches on the front bumper may predate this crash and should be separated from the claim. The repair plan calls for panel replacement, refinishing, and a new lamp assembly. The labor hours written on this estimate run roughly three times above what this scope of work normally needs, so the hours should be reviewed line by line before approval. The invoices themselves show no repeated charges.