Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-584987
Estimate date:	7-18-23
Customer:	Nancy Holt
Phone:	713-555-7692
Insurance claim:	C-1437
Vehicle:	2013 Jeep Cherokee
VIN:	
License plate:	928-636

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$615.96
Right front door shell	1	$545.53
Left quarter panel	1	$347.82
Body labor	13.2 hrs	$899.18
Paint and materials		$655.97
TOTAL		$3,064.46

Appraiser remarks

The rear quarter panel and left taillight assembly show crush and tearing consistent with the reported impact while turning left, and the pattern of deformation follows the direction of force described. Adjacent trim and the bumper bracket also show matching marks. The proposed repair plan covers panel straightening, replacement of the lamp housing, refinishing and recalibration of the blind-spot sensor, and the labor hours listed fit the scope of this damage. No prior damage to this vehicle is known from the records reviewed. Two similar line items entered on the same day are being verified against the shop's invoice history before payment is released.