Guerrero Auto Body

83242 Brian Turnpike Suite 994
League City, TX
Phone 713-555-7464

Repair Estimate

Estimate number:	EST-312999
Estimate date:	2025-06-08
Customer:	Steven Chavez
Phone:	
Insurance claim:	C-1445
Vehicle:	2013 Honda Civic
VIN:	HAXTPUMV05G8T0762
License plate:	142 BVE

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$831.19
Left quarter panel	1	$846.78
Headlamp assembly	1	$501.60
Body labor	29.9 hrs	$2,035.24
Paint and materials		$976.20
TOTAL		$5,191.01

Appraiser remarks

The vehicle shows scraping and a dented rear quarter panel on the passenger side, with a cracked taillight lens and a scuffed bumper cover running into the wheel arch. The pattern of contact matches a sideswipe during a lane change, and the damage sits where that kind of impact would be expected. The repair plan calls for panel straightening, refinishing, and replacement of the lens and bumper cover, and the labor hours requested fit the extent of the work. No earlier damage to the vehicle is known from the inspection or prior records. Two similar charges on the same day are still being reviewed befroe the estimate is finalized.