Patton Collision Center

518 Smith Manor Suite 165
League City, TX
Phone 281-555-6284

Repair Estimate

Estimate number:	EST-695946
Estimate date:	02/10/2025
Customer:	Crystal Yang
Phone:	713-555-1576
Insurance claim:	C-1450
Vehicle:	2023 Jeep Cherokee
VIN:	W2MWVD7295EUA8027
License plate:	LKL 784

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,448.70
Headlamp assembly	1	$1,184.51
Hood panel	1	$714.61
Body labor	33.9 hrs	$2,302.19
Paint and materials		$1,360.93
TOTAL		$7,010.94

Appraiser remarks

Vehicle was struck on the front driver-side corner while turning left. The damage is visible on the bumper cover, the front fender, and the headlamp assembly, with a cracked reinforcement bar noted under the cover. Some of the lower-panel scuffing could have come from this impact or from an older event, and that cannot be settled from the photos alone. No earlier damage to the vehicle is known. The proposed repair plan replaces the bumper cover, fender, and headlamp, and repairs the reinforcement bar, with labor hours that fit the damage described. The billing shows no repeated charges, and the parts list matches the work written up.