Ross Auto Repair

8713 Caleb Brooks Apt. 930
Pasadena, TX
Phone 713-555-3105

Repair Estimate

Estimate number:	EST-936730
Estimate date:	2024-05-21
Customer:	Monica Stout
Phone:	346-555-8195
Insurance claim:	C-1460
Vehicle:	2017 Nissan Altima
VIN:	7GGVJR2P8A5CL7923
License plate:	85-3893W

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$196.58
Left quarter panel	1	$188.08
Right front door shell	1	$174.49
Body labor	6.5 hrs	$440.77
Paint and materials		$257.21
TOTAL		$1,257.13

Appraiser remarks

The vehicle shows crush and scraping along the driver side door, rear quarter panel and the adjacent sill, which matches the side-on contact described at the intersection. Intrusion is limited to the door skin and inner structure, and the paint transfer pattern runs in the expected direction. The proposed plan replaces the front door, rear quarter panel and sill trim, with panel straightening and refinishing on the blended areas. Labor hours align with the scope of work shown. The billing lines contain no repeated charges. Nothing in the file points to prior damage on this vehicle.