Hall Auto Repair

1823 Joanna Harbor
Katy, TX
Phone 713-555-3435

Repair Estimate

Estimate number:	EST-345838
Estimate date:	2024-03-22
Customer:	Diana Burgess
Phone:	713-555-4157
Insurance claim:	C-1463
Vehicle:	2013 Ford F-150
VIN:	UP318B5Z3RKM44893
License plate:	067B9

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$615.51
Left quarter panel	1	$648.99
Right front door shell	1	$347.29
Body labor	27.1 hrs	$1,302.40
Paint and materials		$536.21
TOTAL		$3,450.40

Appraiser remarks

The rear passenger quarter panel and rear door show scrape marks, a cracked taillight lens and paint transfer along the lower edge, which fits the reported sideswipe during a lane change. No earlier damage to the vehicle is known, and the damage pattern matches the described impact. The bills show no repeated charges. The proposed repair plan covers panel replacement, refinishing and lamp replacement, though the labor hours appear a little high for this scope and should be reviewed against standard repair times before approval.